
	<p>कार्यकारी अभियंता यांचे कार्यालय सार्वजनिक बांधकाम भवन, पालघर बांधकाम भवन इमारत, ढवळे रुग्णालय शेजारी, पालघर-बोईसर रोड, ता.जि. पालघर</p>	
<a href="http://www.mahapwd.gov.in">www.mahapwd.gov.in</a>		Email palghar.ee@mahapwd.gov.in
जा.क्र. सा.बां.वि/पालघर/रेशा/ ४८६४	दिनांक - 13 JUN 2025	

प्रति,  
मुख्याध्यापक,  
कनोसा स्कूल CBSC, माणिकपूर  
वसई रोड, ता.वसई जि.पालघर.


विषय : इमारत सुरक्षित असल्याबाबतचा दाखला मिळणेबाबत,  
कनोसा स्कूल CBSC, माणिकपूर वसई रोड, ता.वसई जि.पालघर.  
संदर्भ : १.आपले दि.०५/०५/२०२५ रोजीचा अर्ज.  
२.उपविभागीय अभियंता, सा.बां. उपविभाग क्र.१, वसई यांचे पत्र  
क्र.सा.बां/उवि/वसई/रेशा/६५५ दि.२०/०५/२०२५.

वरील संदर्भित विषयानुसार आपण सादर केलेल्या आवेदन पत्रानुसार आपल्या, कनोसा स्कूल CBSC, माणिकपूर वसई रोड, ता.वसई जि.पालघर. या शाळेच्या इमारतीची या विभागातंगत असलेल्या सहा. अभि. श्रेणी १, सा.बां. उपविभाग क्र.१, वसई यांनी दि.१६/०५/२०२५ रोजी प्रत्यक्ष पाहणी केली असून अहवाल या विभागाकडे सादर केलेला आहे.


त्यानुसार आपण मागणी केल्यानुसार इमारतीचे नॅशनल बिल्डींग कोड - २०१५ नुसार इमारत सुरक्षित असल्याबाबतचे प्रमाणपत्र देण्यात येत आहे.

कृपया पोच दयावी.

सोबत :- प्रमाणपत्र

  
कार्यकारी अभियंता  
सा.बां.विभाग, पालघर

प्रत : सहा. अभि. श्रेणी १, सा.बां. उपविभाग क्र.१, वसई यांना माहितीसाठी रवाना.

  
**PRINCIPAL**  
Canossa School CBSE  
Manickpur, Vasai Road,  
Dist. Palghar - 401202




## BUILDING SAFETY CERTIFICATE

It is Certified that the existing building CANOSSA SCHOOL CBSC, SURVEY NO.30/18(pt), 30/19, 32/2/A, 32/3, 32/4(pt), 33/8, 33/9, 33/10, 33/11, 33/12, 33/13, 33/14, 33/15, 33/16, 33/17, 33/18, 34/1, 34/2, 35/1, 36/1/1, 36/3, 36/4, 36/5, 36/6, 36/7, 36/8, 36/9, 37/1, 37/2, 37/3 of VILLAGE - MANICKPUR, TAL.VASAI, DIST.-PALGHAR is having block(s) / Floor(s) as per details below.

Details of Block(s) in school	Block (1)	Block (2)	Block (3)
No. of Floor(s) in the Block	Ground + Mezz + 2 <sup>nd</sup> floor	Ground + 3 <sup>rd</sup> floor	-

The building is owned /occupied by CANOSSA SCHOOL CBSC, SURVEY NO.30/18(pt), 30/19, 32/2/A, 32/3, 32/4(pt), 33/8, 33/9, 33/10, 33/11, 33/12, 33/13, 33/14, 33/15, 33/16, 33/17, 33/18, 34/1, 34/2, 35/1, 36/1/1, 36/3, 36/4, 36/5, 36/6, 36/7, 36/8, 36/9, 37/1, 37/2, 37/3 of VILLAGE - MANICKPUR, TAL.VASAI, DIST.-PALGHAR have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Works Department on 20/05/2025 in the presence of PRINCIPAL, CANOSSA SCHOOL and that the building/ Premises is fit for occupancy for running school with effect from 20/05/2025 to 19/05/2026 for a period of One years in accordance with rule and subjected to compliance of the specific conditions as appended.

1. In future, if the building has any issues relating to any cracks, collapse and leakage of water, it should be reported to concern department and immediate action should be taken.
2. Should procure fire safety certificate from fire department their recommendations should be followed and updated regularly.
3. Original documents of the building should be kept safely.



Assistant Engineer Gr.1  
P.W.Sub-Division No.1 Vasai

Counter Signed



Executive Engineer  
P.W.Division, Palghar



PRINCIPAL  
Canossa School CBSE  
Manickpur, Vasai Road,  
Dist. Palghar - 401202